

NONCOMPLIANCE REPORT

Attachment to Atlanta Gold Corporation's Discharge Monitoring Reports

January 2017 – The weekly arsenic results for the effluent were 9 ug/L, 12 ug/L, 9 ug/L and 8 ug/L. The one result over the compliance limit was probably due to activity in the adit. The water treatment operator had to replace additional filter material as there was a collapse within the 900 crosscut behind the dam.